

INSPECTION

REPORT

GENERAL DESCRIPTION

Product Description .:	Headphones Gamer HD speakers 3.5/ USB	sound, Led Light,	Microphor	ne omnidir	ectional and
		Report number .:			
		Inspection Date.:		30	
		Service Item .:	☑ PSI	□ IPI	□ DPI
		Service item	□ PM	□ FI	RE-PSI
1		Customer .:	R		
		Customer P.O .:	1854		
	-	Vendor .:			
		Vendor P.O No .:			
		Target Market .:			
		Manufacturer .:			
		Location Area .:	Donggua	an.Gaundo	ng.China

QUANTITY CHECK

Client P.O. # SKU		Quantity	y on PO #	Actual Finished Quantity		
Client P.O. #	SKU	Product Quantity	Cartons Quantity	Finished Quantity	Packed Cartons	
1854	78917	4500	225	4500	225	
Tota	al	4500	225	4500	225	

INSPECTION INFORMATION

Inspection based on					
■Approval Sample	□ Specifications	□P/O#	☑ Photos	□ Drawing	☑Others.:

OVERALL INSPECTION RESULT		FAIL			
Bases On Below	Bases On Below AQL & Approved sample& Remark:				
Approved sample	□Yes ☑ No				
AQL	FAIL	Beyond AQL			
Remark	FAIL	Due to Remark 1 to 3			

PROBLEMATIC REMARKS

- Major and minor defects were beyond AQL standard. Found 60pcs with wrong wrong connection
 cable in package and 75pcs with white mark on product, which was cleanable. The factory said they
 would rework the two problems, which needs to be confirmed by client.
- 2. The barcode on the color box could not be scanned.
- 3. The actual impedance of speaker was beyond the tolerance given by client.
- 4. No anti-cutting board was found when opening cartons.
- The inspector only found air hole in the big poly bag, but without warning text, which the opening was beyond 17cm.
- 6. The factory refused to do all drop tests.
- 7. The test videos will be sent by wetransfer.

Please see below attached photos to demonstrate the above Problematic Remarks:





Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 2 of 40





Remark 1: Found 75pcs with white mark on product, which was cleanable.





Remark 2: The barcode on the color box could not be scanned.



Speaker diameter: 50 mm
Impedance: 20 Ohms±15%
Speaker sensitivity: 115dB ±3dB
Frequency Response: 20Hz-20KHz
Microphone measures: 6mm*2.7mm
Microphone Sensitive: -38±3dB

Reamark 3:The actual impedance of speaker was beyond the tolerance given by client.

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 3 of 40 F0092B JUN15132005





1

Remark 4:No anti-cutting board was found when opening cartons.





Remark 5:The inspector only found air hole in the big poly bag, but without warning text, which the opening was beyond 17cm.

INSPECTION METHODS APPLIED

Inspection	n Criteria -	Acceptable (Quality Level (AQL)			
Inspection service requirement	Final Random Inspection					
Sampling standard performed per	ANSI/ASQC Z1.4-1993 Single sampling plan for normal inspecti (ISO 2859-1, MIL-STD 105E, or BS6001)					
General inspection levels at	1	II	No. of sample size inspected	315PCS		
Acceptable Quality Level (AQL)	Critical		Major	Minor		
for:	Not a	lowed	2.5	4.0		
No. of sample size inspected for :	315	PCS	315PCS	315PCS		
Total No. of packed cartons	225	cartons	Number of cartons oper	shall be the square		
No. of inspected cartons	16	cartons	root of the available cartons quantity.			
Samp	les selected	from the fo	llowing cartons :			
			22,58,10,138,6,188,70,25			

APPEARANCE & FUNCTION INSPECTION

	PO#	1854	Item No #		78917
No.	Details (of Non-Conformity	Critical	Major	Minor
Appear	ance & Visual Defects				
1.	Wrong connection cable	0	60	0	
2.	White mark removable	0	0	75	
3.	Dirty stains removable		0	0	4

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 4 of 40 F0092B JUN15132005



©2002 CQI Quality Consultancy Limited. All rights reserved Foreign material 0 0 0 0 5 Scratch mark **Functional Defects** 0 0 0 6. Safety of product (Zero tolerance, if product hurts the users directly or potential 7.

ally.)		02	46
and the state of t	0	0	0
Total defects found:	0	60	85
Maximum Critical/Major/Minor Allowed:	0	14	21
Samples Checked:	315	315	315
Inspection Result:	V	Beyond A)L

Defect Photo:





Wrong connection cable in package-Major

Wrong connection cable in package-Major





Wrong connection cable in package-Major

Wrong connection cable in package-Major(60pcs)





Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 5 of 40 F0092B JUN15132005





F0092B JUN15132005 Page 6 of 40



F0092B JUN15132005 Page 7 of 40



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 8 of 40



F0092B JUN15132005 Page 9 of 40



F0092B JUN15132005 Page 10 of 40



GENERAL INSPECTION CHECKLIST

#	Inspection Item	Result			Testing Conditions & Requirements /	Sample
#	inspection item	Pass	Fail	Pend	Record	Size
1.	Outside Appearance		V	N/A	Refer to defects on AQLs.	315pcs
2.	General Function Inspection	V		N/A	Refer to defects on AQLs.	315pcs
3.	Product drop with packing			\square		N/A
4.	Product Bare drop			$\overline{\mathbf{V}}$	Factory refused to do these tests.	N/A
5.	Carton Drop test			$\overline{\mathbf{V}}$		N/A
6.	Barcode Scanning test(Outer carton barcode)	☑			It could be read and correct.	5pcs
7.	Barcode Scanning test(color box barcode)		☑		The barcode on the color box could not be scanned	32pcs
8.	Stretching function test	\square			Acceptable.	315pcs
9.	3M tape test	$\overline{\mathbf{A}}$			Acceptable.	8pcs
10.	Call function,microphone function and silent mode check	☑			Meet basic usage.	315pcs
11.	Fitting test	$\overline{\mathbf{A}}$			Meet basic usage.	8pcs
12.	Listen to music and volume adjustment function test	V			Meet basic usage.	315pcs
13.	Rub test	\checkmark			Acceptable.	8pcs
14.	Endurance test	V			Meet basic usage.	5pcs

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 11 of 40



15.	Light function test	V			Meet basic usage.	315pcs
16.	Internal check	V			Acceptable.	2pcs
17.	Cable pull test	V			2kg,acceptable.	8pcs
18.	Headphone sensitivity and frequency response check	V			Acceptable.	8pcs
19.	Headphone impedance	$\overline{\mathbf{A}}$			Acceptable.	8pcs
20.	Microphone sensitivity and frequency response check	V			Acceptable.	8pcs
21.	Microphone impedance				Acceptable.	2pcs
22.	Headphone impedance		V		The actual impedance of speaker was beyond the tolerance given by client.	2pcs
23.	Abuse test	\checkmark		T A	Acceptable.	8pcs
24.	Connector cable function check	V			Meet basic usage.	100pcs
25.	Led light working voltage and current check	V			No accessible sharp points or edges found, meet basic usage.	2pcs
26.	Shaking test	$\overline{\mathbf{V}}$		4	Acceptable.	315pcs
27.	Accessible sharp Point & Sharp edges check (if any,)	V			No accessible sharp points or edges found, meet basic usage.	315pcs
28.	Structure & Workmanship	V			The judge for reference only, subject to problematic remark on 1st page.	3pcs
29.	Odor check	V			No particular smell found, acceptable.	315pcs
30.	Cleanliness check	V		1 2	Acceptable, except defects on AQLs.	315pcs

ON-SITE TESTS (Photos)

- 1. Below photos to demonstrate the technique & process for certain on-site testing item.
- 2. For different products with the same testing item, only one photo will be taken as evidence.
- 3. It reflects the actual test result under the on-site testing condition provided, the testing result
- 4. can't be a documentary evidence for any disputes, for your reference only.



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 12 of 40 F0092B JUN15132005





3M tape test

F0092B JUN15132005 Page 13 of 40


3M tape test





Page 14 of 40 F0092B JUN15132005





Page 15 of 40 F0092B JUN15132005





Page 16 of 40 F0092B JUN15132005




F0092B JUN15132005 Page 17 of 40



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.


Page 18 of 40 F0092B JUN15132005





Page 19 of 40 F0092B JUN15132005

©2002 CQI Quality Consultancy Limited. All rights reserved 45.0 48.3 51.0 57.0 60.0 Microphone sensitivity and frequency response Microphone sensitivity and frequency response check check 000 ■ 频率網应(L) 组括 PASS + THO(L) . IN SEC. CLESS D. COURSE . C TO RE 44 Microphone sensitivity and frequency response Microphone sensitivity and frequency response check check



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 20 of 40


Abuse test



©2002 CQI Quality Consultancy Limited. All rights reserved Abuse test Abuse test SK530303 Led light working voltage check Led light working current check Shaking test Shaking test

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 21 of 40 F0092B JUN15132005





Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 22 of 40 F0092B JUN15132005



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 23 of 40 F0092B JUN15132005



©2002 CQI Quality Consultancy Limited. All rights reserved 17 18 19 20 21 22 23 24 25 26

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 24 of 40 F0092B JUN15132005



©2002 CQI Quality Consultancy Limited. All rights reserved Speaker diameter Plug size Microphone dimension Microphone dimension

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Microphone dimension

F0092B JUN15132005 Page 25 of 40

USB port size





Nil

USB port size Nil

ON-SITE MEASUREMENT FOR TECHNICAL DATA

Item No:	Check point	Parameter required on PO	Parameter required on unit packaging	Overall size of products	
	Headphone size 195x220mm		N/A	200x210mm	
	Cable length	2.1m	N/A	2.3m	
78917	Speaker diameter	50 mm	N/A	50.85mm	
	Microphone 6mm*2.7mm measures		N/A	5.99x2.72mm	
	Connector	3.5mm	N/A	3.55mm	

300	Item No:	Product net weight for single piece	Product net weight (with unit packing)	Gross weight of outer carton (PO required)	Gross weight (printed on outer carton)	Actual G.W. (+/- 5%)
	78917	401.49g	532.5g	N/A	11.8kgs	11.88kgs

Item No:	Carton size(LxWxH) (PO required)	Carton size(LxWxH) (Printed on Carton)	Actual Carton size(LxWxH) (+/-5%)
78917	N/A	N/A	57.5x42x45cm

Item No:	Product with package size(LxWxH) (PO required)	Product with package size(LxWxH) (Printed on Carton)	Actual Product with package size(LxWxH) (+/-5%)
78917	200x110x210mm	N/A	197x110x211mm

Supplier	Inspector	Supervisor		rvisor	Your Decision for the Inspection		
Nick Lee Steven &David	☑ Dick	F	☐ Mark W	□Agree with result	Customer Sign.	Sign. Date	
	□Jeff	L	□Allen G	□Accept	N/A	N/A	
	rs have notified nent until get fi				☐Other Your Comments.:	N	/A

Factory's Co-operation	□Good	✓ Average	□Poor	□Very bad	- 6
Weather Conditions	□Sunny	☑ Cloudy	□Rainy	□N/A	

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.




Inspection Site ☑ QC Room ■ Warehouse □Harbor ■Workshop

PHOTO DOCUMENT



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 27 of 40 F0092B JUN15132005



Page 28 of 40 F0092B JUN15132005



F0092B JUN15132005 Page 29 of 40



F0092B JUN15132005 Page 30 of 40





F0092B JUN15132005 Page 31 of 40



Color box size

Page 32 of 40 F0092B JUN15132005

Color box size



F0092B JUN15132005 Page 33 of 40



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 34 of 40 F0092B JUN15132005



Product view

F0092B JUN15132005 Page 35 of 40

Product view



Page 36 of 40 F0092B JUN15132005



Page 37 of 40 F0092B JUN15132005



F0092B JUN15132005 Page 38 of 40





Product view

Product view





Cargos stacking

Factory building view





Office building view


Factory name

Page 39 of 40 F0092B JUN15132005





End of the report



F0092B JUN15132005 Page 40 of 40