

INSPECTION REPORT

GENERAL DESCRIPTION

Product Description .:				
	Inspection Date.:		34	-20
	Service Item .:	☑ PSI	□ IPI	□ DPI
	octvice item	□ PM	□ FI	☐ RE-PSI
	Customer .:	111	27.00	
	Customer P.O .:			
	Vendor .:			
	Vendor P.O No .:			
	Target Market .:			
	Manufacturer .:			
	Location Area .:	Shandon	g,China	

QUANTITY CHECK

Client P.O. #	Item No	Quantity	y on PO #	Actual Finished Quantity		
Client P.O. #	item No	Product Quantity	Cartons Quantity	Finished Quantity	Packed Cartons	
Mini harvester	GT-1.5 model	1	1	1	0	
То	tal	1	1	1	0	

INSPECTION INFORMATION

Inspection based on					
□Approval Sample	□ Specifications	☑ P/O#	☐ Photos	□ Drawing	Others.:

OVERALL INSPECTION RESULT		FAIL
Bases On Be	low AQL & App	roved sample& Remark:
Approved sample	□Yes ☑ N	0
AQL	FAIL	Actual Finding
Remark	FAIL	Due to Remark 1 ~ 6

PROBLEMATIC REMARKS

- The manual startup could not work, factory said the machine has electric startup. Need to be confirmed.
- 2. No packing was packed by factory when inspector arrival at factory, there will be some impurities such as fallen leaves on the machine.
- No manual operation offered by factory and can not perform the operation function on site,, pls check the video.
- 4. Found some rust and scratch mark on the handle.
- 5. Found some warning labels were in Chinese.
- No rating label and manufacture information for the whole machine, but only the original info of the Diesel engine and battery.
- 7. For operation weight/production efficiency/grain receiving mode/feeding amount/Total loss rate/impurity content can not been tested on site.

Please see below attached photos to demonstrate the above Problematic Remarks:





1

Remark 2. No packing was packed by factory when inspector arrival at factory, there will be some impurities such as fallen leaves on the machine.



Remark 4 . Found some rust and scratch mark on the handle.
















Remark 6: No rating label and manufacture information for the whole machine, but only the original info of the Diesel engine and battery.

INSPECTION METHODS APPLIED

Inspection	on Criteria - Acceptab	le Quality Level (AQL)		
Inspection service requirement		Final Random Inspectio	n	
Sampling standard performed per	ANSI/ASQC Z1.4-19 (ISO	93 Single sampling plar 2859-1, MIL-STD 105E, or		
General inspection levels at	ı	No. of sample size inspected	1	PCS
Acceptable Quality Level (AQL)	Critical	Major		Minor



for :	Not allowed 1pcs			
No. of sample size inspected for :			1pcs	1pcs
Total No. of packed cartons	Ĩ	cartons	Number of cartons op	en shall be the square
No. of inspected cartons	1	cartons		
Sample	s selecte	d from the fo	llowing cartons:	
Comments.:			in the second second second	

APPEARANCE & FUNCTION INSPECTION

	PO #	Q20201231	Item No	#	1	
No.		Details of Non-Conformity	10	Critical	Major	Minor
Appeara	nce & Visual Defe	ects			100	
1.		poor painting	()	0	0	0
Function	nal Defects		18			
2.		Manual startup not work		0	1	0
	of product (Zer or potentially.)	o tolerance, if product hu	rts the users			
3.		Nil	4	0	0	0
		Total	defects found:	0	1	0
		Maximum Critical/Major/N	linor Allowed:	0	0	0
		Sam	ples Checked:	1	1	1
		Insp	ection Result:		FAIL	
Defect P	hoto:					
		1		1		

GENERAL INSPECTION CHECKLIST

-	# Inspection Item		Result		Testing Conditions & Requirements /	Sample
#			Fail	Pend	Record	Size
1.	Outside Appearance			N/A	Refer to AQL	1pcs
2.	General Function Inspection		☑	N/A	Refer to AQL	1pcs
3.	Size check			☑	Header width: 1010mm Crawler width : 290mm Dimension: 3280*1470*1350mm	1 pcs
4.	Check list			V	Pls refer to remarks	1pcs

ON-SITE TESTS (Photos)

- 1. Below photos to demonstrate the technique & process for certain on-site testing item.
- 2. For different products with the same testing item, only one photo will be taken as evidence.
- 3. It reflects the actual test result under the on-site testing condition provided, the testing result can't be a documentary evidence for any disputes, for your reference only.






Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.










































Supplier	Inspector	Supe	rvisor	Your Decision for the Inspection		ection		
Alisa	Dick F ☐ Mark W ☐ Agree with result ☐ Conditional		Customer Sign.	Sign. Date				
Allea	LIIC	□Jeff L	□Allen G	□Accept	□Accept	□Accept	N/A	N/A
	rs have notified			Other	(17,777,00)	117720		
effect shipn	effect shipment until get final approval from you.			Your Comments.:	N.	A		

Factory's Co-operation	□Good	☑ Average	□Poor	□Very bad
Weather Conditions	□Sunny	☑ Cloudy	□Rainy	□N/A
Inspection Site	□QC Room	☑ Warehouse	□Workshop	□Harbor

PHOTO DOCUMENT

Warehouse



End of Report