1,2,3



# INSPECTION

# REPORT

## **GENERAL DESCRIPTION**

Product Description .: Foldable rucksack					
	Report number .:				
	Inspection Date.:		05		
	Service Item .:	☑ PSI	□ IPI	□ DPI	
		□ PM	□ FI	□ RE-PSI	
	Customer .:	Nahrin Swisscare			
	Customer P.O .:	M16-016NA			
garden-	Vendor .:	1			
	Vendor P.O No .:	1			
	Target Market .:	Italy 🥖			
	Manufacturer .:	1	-		
	Location Area .:	Xiamen, F	Fujian, Chir	na PRC	

#### QUANTITY CHECK

Client P.O. #	Item No	Quantity	y on PO #	Actual Finished Quantity		
	itelli No	Product Quantity	Cartons Quantity	Finished Quantity	Packed Cartons	
M16-016NA	6-016NA Foldable rucksack		100	1	1	
Tot	al	6000	100	1	1	

#### INSPECTION INFORMATION

Inspection based on  □Approval Sample	12	☑ P/O#	□ Photos	☐ Drawing	☐ Others.:
OVERALL IN	NSPECTION		Actual	Due to	Remark #.:

Finding

## PROBLEMATIC REMARKS

Remark #.: 1, For all inspected samples, found visible uneven stitches along the 4 edges of patch.

Remark #.: 2, Slight Off Center For patch-5PCS Out of 32PCS-Major Defect

Remark #.: 3, The Fabric is Easy to Wrinkle for All Samples Inspected

#### Remark # .:

4 One Site Drop in Comments:

RESULT

- 4.1 15 pcs of factory's workers have been working for this order, but 5 workers were off duty.
- 4.2 All main fabric and accessories already finished and arrived in the small workshop, workers were on the process of production.
- 4.3 Around 600pcs of bags have finished the stitching and sewing process, and put in the big wooden box, await for the next step of thread ends trimming and QC & packing process.
- 4.4 As per factory's plan, 29th tomorrow, the quality of finished bags will be around 1500pcs, when all parts and accessories finished stitching and sewing process (Semi-assembly process.)
- 4.5 Factory promised that they would be working overnight if necessary to catch the date of shipment.
- 4.6 Factory had been notified of the actual finding & relative quality problem, who also agreed to pay more attention for the next step, especially for the QC-checking process before packing.
- 4.7 Export cartons and PP bags will be arrived in factory till tomorrow.
- 4.8 According to factory's comments, 300pcs of bags have been shipped out to client by Air.

Please see below attached photos to demonstrate the above Problematic Remarks:

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 1 of 20 F0092B JUN15132005



11 32 33 34 35 36 37 38 39 40 41 42 43 29 30 31 32 33 34 35 36 37 38 39 40 41 42 Remark #1-Remark #1-For all inspected samples, found visible uneven stitches along the For all inspected samples, found visible uneven stitches along the 4 edges of patch (2). 4 edges of patch (1). Remark #1-Remark #1-For all inspected samples, found visible uneven stitches along the For all inspected samples, found visible uneven stitches along the 4 edges of patch. (3) 4 edges of patch. (4) Remark #1-Remark #1-For all inspected samples, found visible uneven stitches along the For all inspected samples, found visible uneven stitches along the 4 edges of patch. (5) 4 edges of patch. (6) 3 24 25 26 27 28 29 30 31 32 33 38 35 36 37 38 39 4 Remark #2-Remark #3-The Fabric is Easy to Wrinkle for All Samples Inspected (1) Slight Off Center For patch-5PCS Out of 32PCS-Major Defect


Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 2 of 20 F0092B JUN15132005

©2002 CQI Quality Consultancy Limited. All rights reserved









Remark #3The Fabric is Easy to Wrinkle for All Samples Inspected (3)

#### INSPECTION METHODS APPLIED

Inspection	n Criteria -	Acceptable (	Quality Level (AQL)			
Inspection service requirement	Final Random Inspection					
Sampling standard performed per	ANSI/ASC	C Z1.4-1993 ( ISO 28	Single sampling plan 59-1, MIL-STD 105E, or	for normal inspection BS6001)		
General inspection levels at		II	No. of sample size inspected	20 PCS *4+32PCS *1		
Acceptable Quality Level ( AQL)	Critical		Major	Minor		
for:	Not allowed		2.5	4.0		
No. of sample size inspected for :	20 PCS *4	4+32PCS *1	20 PCS *4+32PCS *1	20 PCS *4+32PCS *1		
Total No. of packed cartons	1	cartons	Number of cartons op	en shall be the square		
No. of inspected cartons	/ cartons root of the available cartons quantit					
	les selected	from the fo	llowing cartons :			
Comments.: /			¥			

## APPEARANCE & FUNCTION INSPECTION

	PO#		Item No #		
No.	Details	Critical	Major	Minor	
Appearanc	e & Visual Defects			X 55°	(V)
1.	See below "Du	1	1	1	
Functional	Defects				(); (c)
2.	See below "Du	ring Production Inspection"	1	1	1
	product ( Zero tole potentially.)	rance, if product hurts the users	S	e e	16:
3.	See below "Du	1	1	1	
		Total Defects found	:		
4	Max	imum Critical/Major/Minor Allowed	:		
		Samples Checked	:	_	
•		Inspection Result	:	1	
Defect Pho	to:			119.000	
	1		1		

# **During Production Inspection**

- I. Workshop
- II. Production Process
- III. On Site View
- IV. Parts Inspection
- V. Finished Stitching & Sewing Bags Inspection

Workshop

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 3 of 20 F0092B JUN15132005





Mid-Yellow Own Workshop View (0)



Mid-Yellow Own Workshop View (1)



Mid-Yellow Own Workshop View (2)



Mid-Yellow Own Workshop View (3)

# Mid-Yellow's Sub-Contractor Factory



Sub-Contractor Factory-Workshop-View (1)



Sub-Contractor Factory-Workshop-View (2)



Sub-Contractor Factory-Workshop-View (3)



Sub-Contractor Factory-Workshop-View (4)

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 4 of 20 F0092B JUN15132005



©2002 CQI Quality Consultancy Limited. All rights reserved Sub-Contractor Factory-Workshop-View (5) Sub-Contractor Factory-Workshop-View (6) Sub-Contractor Factory-Workshop-View (8) Sub-Contractor Factory-Workshop-View (7) Sub-Contractor Factory-Workshop-View (9) Sub-Contractor Factory-Workshop-View) **Production Process** 

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Production Process View (1)

F0092B JUN15132005 Page 5 of 20

Production Process View (10)



©2002 CQI Quality Consultancy Limited. All rights reserved Production Process View (11) Production Process View (12) Production Process View (14) Production Process View (13) Production Process View (15) Production Process View (16) Production Process View (17) Production Process View (18)

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 6 of 20 F0092B JUN15132005



©2002 CQI Quality Consultancy Limited. All rights reserved Production Process View (19) Production Process View (2) Production Process View (20) Production Process View (21) Production Process View (22) Production Process View (23) Production Process View (25) Production Process View (24)

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 7 of 20 F0092B JUN15132005





Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 8 of 20 F0092B JUN15132005





Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 9 of 20





Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 10 of 20 F0092B JUN15132005



©2002 CQI Quality Consultancy Limited. All rights reserved Back Panels View (1) Back Panels View (2) Back Panels View (4) Back Panels View (3) Back Panels View (6)-Thred Ends Need To Back Panels View (5)-Thred Ends Need To Trim On Next Process-1PC Trim On Next Process-1PC

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

4. Front Main Part

Back Panels View (7)-Open Seam Need To

Pick Out-Major Defect-1PC

Page 11 of 20 F0092B JUN15132005

Back Panels View (8)-Loose Stitches-Minor

Defect-1PC





Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 12 of 20 F0092B JUN15132005



©2002 CQI Quality Consultancy Limited. All rights reserved Bags Finished Stitching-Sewing-Product View (18)






Bags Finished Stitching-Sewing-Product View (19)

Bags Finished Stitching-Sewing-Product View (20)







Bags Finished Stitching-Sewing-Product View (22)



Bags Finished Stitching-Sewing-Product View (23)



Bags Finished Stitching-Sewing-Product View (24)







Bags Finished Stitching-Sewing-Product View (26)

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 13 of 20







Bags Finished Stitching-Sewing-Product View (27)



Bags Finished Stitching-Sewing-Product View (29)

Bags Finished Stitching-Sewing-Product View (30)





Bags Finished Stitching-Sewing-Product View (31)

Bags Finished Stitching-Sewing-Product View (32)





Bags Finished Stitching-Sewing-Product View (34)

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 14 of 20 F0092B JUN15132005



32 Samples to be inspected



32 Samples to be inspected



Pen Mark-Minor Defect-1PC



Pen Mark-Minor Defects-1PC



Color Stain-Minor Defect-1PC



Double Stitches At Edge Of Patch-Minor Defect-1PC



High-Low Side Panel-Major Defect (1)




High-Low Side Panel-Major Defect (2)

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 15 of 20 F0092B JUN15132005







# GENERAL INSPECTION CHECKLIST

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 16 of 20 F0092B JUN15132005



	imports saler		Result		©2002 CQI Quality Consultancy Limited. All no	
#	Inspection Item	Pass	Fail	Pend	Testing Conditions & Requirements / Record	Sample Size
1.	Outside Appearance			N/A	1	1
2.	Carton Drop test				I	1
3.	Product dimension/weight				1	1
4.	Carton dimension/Weight				1	1
5.	Compared with sample including the measurement/ color/ shade/accessories		_		1	
6.	Pull test for all metal parts	V			Found accepted, after test.	8pcs/ item
7.	Seam strength for all part/pocket/ the end handle/Shoulder strap/	☑			Found accepted, after test.	5pcs/ item
8.	Number of stitches per inch				6~7stitches / inch.	3pcs/ite m
9.	Odor check	V			No particular smell found, acceptable.	3pcs
10.	Color shading check -within same piece -among all inspected piece	☑			Found accepted.	125pcs item
11.	Adhesion Check for Silk screen printing/Coating	V			Found accepted.	3pcs/ite m
12.	Rub test on all marking or printing					1
13.	Rub test to check color fastness of the fabric and all accessories(i.e labels)					1
14.	General Function Inspection/Fitting check / Assembly test ( if any,)			N/A		1
15.	Actual performance test/Loading test	V			Found Accepted, after test under the condition of 10kgs for 2 hour.	5pcs/ item
16.	Abuse test/Fatigue test for all adjustable parts	M			Found Accepted, Test Zipper/Velcro 20 times	13pcs/i em
17.	Barcode Scanning test				1	1
18.	Fabric quality(Check the thickness with GSM)	9			1	1
19.	Accessible sharp Point &				1	1
20.	Structure & Workmanship -symmetry design -priting, paiting check				1	,
	-no tube goes out of handle					
21.	Ease of use check				I	1
22.	Cleanliness check	V			Acceptable, except Defects on AQLs.	3pcs

### ON-SITE TESTS (Photos)

- 1. Below photos to demonstrate the technique & process for certain on-site testing item.
- 2. For different products with the same testing item, only one photo will be taken as evidence.
- 3. It reflects the actual test result under the on-site testing condition provided, the testing result
- 4. can't be a documentary evidence for any disputes, for your reference only.

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 17 of 20 F0092B JUN15132005





Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 18 of 20 F0092B JUN15132005



Silk-Screen Printing Adhesion Test



Static Loading Test for Back Strips at 10Kgs x 2Hours-Found OK



Static Loading Test for Handle Strip at 10Kgs x 2Hours (2)-Found **OK After Test** 



Static Loading Test for handle strip at 10Kg



Stitches Density-6-7Stitches per Inch-Found OK After Test-Found **OK After Tes** 



Stitches Density-6-7Stitches per Inch

#### FOLLOW-UP ACTION:

PLEASE ADVISE						
nce of certificate [] Re-FINAL charge will be covered by	supplier					
nce of non-negotiable actual finding report [] Other	S 5000					
nments.:						

Supplier	Inspector	Supervisor		Your Decision for the Inspection		
Kaven Roy	☑ Dick F	☐ Mark W	□Agree with result	Customer Sign.	Sign. Date	
	Koy	□Jeff L	□Allen G	□Accept	N/A	N/A
Our inspectors have notified supplier/factory not to effect shipment until get final approval from you.			Other  Your Comments.:	N	Ά	

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 19 of 20 F0092B JUN15132005



Factory's Co-operation	□Good	☑ Average	□Poor	□Very bad
Weather Conditions	□Sunny	☑ Cloudy	□Rainy	□N/A
Inspection Site	□QC Room	☑ Warehouse	□Workshop	□Harbor

End of the report



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 20 of 20 F0092B JUN15132005