

INSPECTION

REPORT

GENERAL DESCRIPTION

Product Description .:	Baby guardrail with extension	on	5		
/ F	an III	Report number .:			
		Inspection Date.:			
1		Service Item .:	☑ PSI	□ IPI	□ DPI
			□ PM	□ FI	RE-PSI
		Customer .:		36	
		Customer P.O .:			
		Vendor .:			
		Vendor P.O No .:			
		Target Market .:			
Ve-3 (80) 160	September 1980 - Village 1980	Manufacturer .:			
	STATE OF THE PARTY AND ADDRESS OF THE PARTY AN	Location Area .:	Zhejiang,	China	
SULANITITY OFFICE					

QUANTITY CHECK

Client P.O. # Item No	Itom No	Quantity	y on PO #	Actual Finished Quantity		
	Product Quantity	Cartons Quantity	Finished Quantity	Packed Cartons		
3222	83244	500	500	500	480	
То	tal	500	500	500	480	

Inspection Environment

Factory's Co-operation Weather Conditions	☑Good ☑Sunny	☐ Average ☐ Cloudy	□Poor □Rainy	□Very bad □N/A
Inspection Site	□QC Room	☑ Warehouse	□Workshop	□N/A □Harbor
Inspection Done on	□Table	□Casual table	☑Ground	□N/A
Cleanliness	□Clean	✓ Average	□Poor	□Very bad
Lighting	☐Sufficient Daylight	☑ Insufficient Daylight	□Dark	□N/A
Cargo Storage	Orderly	☑ Disorderly	□Messy	□N/A
Quantity check	☑ The carton quant inspector	☐ The carton quantity is given by factory		

OVERALL INSPECTION RESULT		FAIL		
Bases On Below AQL & Approved sample& Remark:				
Approved sample	□Yes ☑ No	•		
AQL	FAIL	Beyond AQL		
Remark	FAIL	Due to Remark 2,3,4		

PROBLEMATIC REMARKS

- 1. When the inspector arrived at the factory, found 96% of products were packed. Please refer to the quantity table.
- 2. Found the actual height of the product was 780mm instead of 885mm given by DS.But it met the requirement of the measurement example 775m in DS.Need to be confirmed by client.
- 3. Found the actual logo position was to the left instead of the center shown in DS.
- 4. Found there were more or less poor welding on the edge of each round tube. And the bottoms of the square pipes on both sides had different degrees of visible welds.
- The color at the top of the back of the manual was found to have a slight bleed through. And there was a slight color difference between the actual manual and the photos given by DS.
- 6. No desiccant was found in the product packaging.

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not expressed by each of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.



- 7. Found the products were only packaged in color boxes, and there were metal nails on the side.
- 8. There was no warning on the PE bag.
- 9. The label information in DS was too blurry, please check the actual picture.
- 10. There was a Chinese mark.
- 11. Due to the way of product packaging, the factory only allowed inspector to unpack 15pcs for inspection. The remaining 65pcs could only be inspected through PE bags.
- 12. The factory couldn't provide the laboratory test report.
- 13. As the manual was in Spanish, the functions, safety & quality directions and points for attention of the product could not be completely checked during the inspection. The inspector inspected the products based on data sheet given by client and the process prepared by QA team.

Please see below attached photos to demonstrate the above Problematic Remarks:






Height

885mm ±5%



Remark 2: Found the actual height of the product was 780mm instead of 885mm given by DS.But it met the requirement of the measurement example 775m in DS.






Branding (Color print sticcker)

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.


Page 2 of 25 F0092B JUN15132005





Remark 4: Found there were more or less poor welding on the edge of each round tube. And the bottoms of the square pipes on both sides had different degrees of visible welds.

Page 3 of 25 F0092B JUN15132005



Remark 5: The color at the top of the back of the manual was found to have a slight bleed through. And there was a slight color difference between the actual manual and the photos given by DS.



Remark 7: Found the products were only packaged in color boxes, and there were metal nails on the side.

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exponent buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 4 of 25 F0092B JUN15132005



Remark 8: There was no warning on the PE bag.



Remark 9: The label information in DS was too blurry, please check the actual picture.



Remark 10: There was a Chinese mark.

	ii Cilteria -	And the second s	Quality Level (AQL	P.			
Inspection service requirement		Final Random Inspection					
Sampling standard performed per	ANSI/ASQC Z1.4-1993 Single sampling plan for norm (ISO 2859-1, MIL-STD 105E, or BS6001)						
General inspection levels at	1	Ш	No. of sample size	ze 80	PCS		
Acceptable Quality Level (AQL)	Critical		Major		Minor		
for:	Not a	llowed	2.5		4.0		
No. of sample size inspected for :	80pcs		80pcs	cs 80pcs			
Total No. of packed cartons	500	cartons	Number of carton	s open sha	III be the square		
No. of inspected cartons	80	cartons	root of the ava	ilable carte	ons quantity.		
Samp	les selected	from the fol	lowing cartons :		18 NA		
Comments.: No carton number	on shippin	g mark.	7,000				
Inspection based on							
A CONTRACT OF THE PROPERTY OF		/O#			The second secon		

APPEARANCE & FUNCTION INSPECTION

PO#	3222	Item No #	83244		
Details	Critical	Major	Minor	%	
Appearance & Visual Defe					

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not experience buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 5 of 25



©2002 CQI Quality Consultancy Limited. All rights reserved Malposition 0 0 1.25% Raw edge 0 0 1.25% Welding slag 0 0 1 1.25% 3. 1.25% 4. Foreign object 0 0 1 5. Abrasion mark 0 0 5 6.25% 2.5% **Scratches** 0 0 2 6. 7. Dirty mark 0 0 3 3.75% **Functional Defects** Nil 0 0 0 Safety of product (Zero tolerance, if product hurts the users directly or potentially.) Nil 1. 0 0 Total defects found: 0 2 12 7 Maximum Critical/Major/Minor Allowed: 0 5 80 80 80 Samples Checked: Within Within Beyond Sub-AQL Result: AQL AQL Overall AQL Inspection Result: ☑ Beyond AQL PS: Batch defects exceeding 5% will be recorded in remarks again. Defect Photo: Malposition-maj Raw edge-maj

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exponent buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Welding slag-min

Page 6 of 25 F0092B JUN15132005

Foreign object-min



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 7 of 25 F0092B JUN15132005



GENERAL INSPECTION CHECKLIST

#	Increation Item		Result		Testing Conditions & Requirements /	Sample
#	Inspection Item		Pass Fail Pend		Record	Size
1.	Outside Appearance		☑	N/A	Refer to defects on AQLs.	80pcs
2.	General Function Inspection	$\overline{\mathbf{V}}$		N/A	Refer to defects on AQLs.	15pcs
3.	Assembly test	$\overline{\mathbf{A}}$			Meet basic usage.	10pcs
4.	Loading test(80kg)	$\overline{\mathbf{A}}$			Meet basic usage.	10pcs
5.	Imitative impact test	$\overline{\mathbf{A}}$			Tested by hand. Meet basic usage.	5pcs
6.	Abuse test	$\overline{\mathbf{A}}$			Found acceptable.	10pcs
7.	Rubber test	$\overline{\mathbf{A}}$			Found acceptable.	3pcs
8.	Adhesion Check for Coating	$\overline{\mathbf{A}}$			Found acceptable.	1pc
9.	Barcode Scanning test	$\overline{\mathbf{A}}$		1 20	Readable&correct.	5pcs
10.	Carton Drop test			☑	The factory was only allowed to fall six from the height of 60cm.	1ctn
11.	Color shading check				Found acceptable.	15pcs
12.	Accessible sharp Point & Sharp edges check (if any,)				No accessible sharp points or edges found, meet basic usage.	15pcs
13.	3. Structure & Workmanship				The judge for reference only, subject to problematic remark on 1st page.	3pcs
14.	Odor check	$\overline{\mathbf{V}}$			No particular smell found, acceptable.	15pcs

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 8 of 25 F0092B JUN15132005



 $\overline{\mathbf{V}}$ 15. Cleanliness check Acceptable, except defects on AQLs. 80pcs


ON-SITE TESTS (Photos)

- 1. Below photos to demonstrate the technique & process for certain on-site testing item.
- 2. For different products with the same testing item, only one photo will be taken as evidence.
- 3. It reflects the actual test result under the on-site testing condition provided, the testing result can't be



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not expnerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.


Page 9 of 25 F0092B JUN15132005



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 10 of 25 F0092B JUN15132005





ON-SITE MEASUREMENT FOR TECHNICAL DATA

Item No:	Parameter required on PO	Parameter required on unit packaging	Overall size of products
83244-product	820mmx125mmx885mm ±5%		820mmx128mmx <mark>780</mark> mm
83244-holder	455mm*130mm*31mm	-	452mm*128mm*31mm/180g

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 11 of 25 F0092B JUN15132005



	02002	Odi dounty	Consultancy Limited.	/ III rigitto rocorvou
±5%/194g				

Item No:	Product net weight	Product net weight (with unit packing)	Gross weight of outer carton (PO required)	Gross weight (printed on outer carton)	Actual G.W. (+/- 5%)	
83244- product	3940g (spec as 4016g ±5%)	37.3	4500g ±5%		4700g	

Item No:	Carton size(LxWxH) (PO required)	Carton size(LxWxH) (Printed on Carton)	Actual Carton size(LxWxH) (+/-5%)
83244	750*820*60mm ±5%	•	760x828x55mm

Supplier	Inspector	Supervisor		rvisor	Your Decision for the Inspection			
Selena Peter	☑ Dick			□Agree with result	Customer Sign.	Sign. Date		
	□Jeff	L	□Allen G	□Accept	N/A	N/A		
	Our inspectors have notified supplier/factory not to effect shipment until get final approval from you.			☐Other Your Comments.:	N/	'A		


PHOTO DOCUMENT




Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not experience buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 12 of 25





Page 13 of 25 F0092B JUN15132005



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 14 of 25 F0092B JUN15132005



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.


Page 15 of 25 F0092B JUN15132005





F0092B JUN15132005 Page 16 of 25





Page 17 of 25 F0092B JUN15132005



Page 18 of 25 F0092B JUN15132005



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 19 of 25




Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 20 of 25 F0092B JUN15132005



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

F0092B JUN15132005 Page 21 of 25



F0092B JUN15132005 Page 22 of 25




F0092B JUN15132005 Page 23 of 25



Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 24 of 25 F0092B JUN15132005





End of the report

Notice: This report is issued by the company under its General Conditions for inspection, assessment, technical assistance. The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sales. Stipulations to the contrary are not binding on the company. The company's responsibility under this report is limited to proven negligence and will in no case be more than eight times the amount of the fees or commission, which will be paid by free Man-day.

Page 25 of 25 F0092B JUN15132005